#### INTRODUCTION FOR VENDOR INFORMATION HAZARDOUS WASTE STUDY SERIES JANUARY 28, 2000

The following communication was provided by the Environmental Laboratory Accreditation Program (ELAP) in 2000 to vendors, who showed interest in providing solid and non-aqueous performance evaluation study samples for the ELAP certification of laboratories. This communication is being posted on the ELAP website as instructed by management. Since none of the vendors have contracts with ELAP, the communication was provided as a guideline for the vendors to use in the preparation of hazardous waste performance evaluation samples. Information that is needed by ELAP for administering future studies to evaluate laboratory performance have been shaded in this posting.

#### DEPARTMENT OF HEALTH SERVICES

2151 BERKELEY WAY BERKELEY, CA 94704-1011 510)540-2800

January 28, 2000

VENDOR INFORMATION
ELAP PERFORMANCE EVALUATION STUDY PROGRAM
HAZARDOUS WASTE (HW) STUDY SERIES
CHEMISTRY

California State Environmental Laboratory Accreditation Program (ELAP) has a two-tiered certification program for laboratories performing testing of environmental samples: NELAP accreditation program; ELAP certification program. The terminology "proficiency testing studies" or "PT studies" refers to the NELAP accreditation program. The term "performance evaluation studies" or PE studies" refers to the California ELAP certification program. The information provided in this communique describes the ELAP certification program, which is California's regular certification program.

Since the NIST accreditation program of vendors did not include hazardous waste matrices, a vendor listing different from that of NIST's has been provided to our laboratories. This listing has been enclosed along with the analytes list. If you cannot provide the listed analytes in the year 2000, and are not able to meet California's needs, please contact Jane Jensen at (510) 540-2800 by February 14, 2000, in order for your company's name to be removed from the listing. Please provide the request in writing to Jane Jensen at the above address.

Laboratories certified in California are required to submit results using all methods requested for certification. Thus, the laboratories have been instructed to make copies of the blank report forms to facilitate such reporting to the vendor of choice. Laboratories are permitted to report multiple results for the 1same analytes from one sample, since identical reported results are technically not probable with the use of different analytical methods.

Since California certification includes mobile laboratories and auxiliary laboratories/units associated with stationary/parent laboratories, multiple samples may be requested by the stationary/parent laboratory. Each mobile laboratory must possess its own EPA laboratory ID code, in order for the results to be applied to the mobile laboratory. If an auxiliary unit desires to participate in a performance evaluation study, then it must possess its own EPA laboratory ID code in order for the results to be differentiated from the parent laboratory. If an EPA laboratory ID code is not made available to the vendor by the laboratory, please remind the laboratory to contact Fred Choske at (510) 540-2800, immediately.



Page 2 of 2 January 28, 2000 Vendor Information

Enclosed is information for the California ELAP certification program information is for the vendor alone and not to be shared with others.

Numerous vendors have inquired about the number of participants for the analytes which appear on the enclosed list. The estimated number of participants for some of the analytes and methods have been enclosed.

Please contact Jane Jensen at (510) 540-2800, if you have any questions Your cooperation is greatly appreciated.

Sincerely,

George C. Kulasingham, Ph.D. Program Chief

( Signed by JJ )

Jane Jensen

Environmental Laboratory Accreditation Program

Enclosure

List of vendors List of analytes/methods Estimated Number of Participants Vendor Information

ELAP HW Study Requirements Hazardous Waste Performance Evaluation Sample Requirements Hazardous Waste Performance Evaluation Sample Specifications Example/Hazardous Waste Study Instructions

# VENDORS PERFORMANCE EVALUATION STUDY SAMPLE HAZARDOUS WASTE MATRICES (January 2000)

Provider	Address/Telephone/FAX/E-mail	Contact
Absolute Standards, Inc.	P.O. Box 5585 Hamden, CT 06518 800-368-1131 FAX 800-410-2577 Absolutest@aol.com	Stephen J. Arpie
ERA (Environmental Resource Associates)	5540 Marshall Street Arvada, CO 80002 800-372-0122 FAX 303-421-0159 qcstds@aol.com	Chuck Wibby
New York State	Environmental Laboratory Approval Program NYSDOH, Wadsworth Center P.O. Box 509 Albany, NY 12201 518-485-5570 FAX 518-485-5568 Caruso@wadsworth.org	Matthew Caruso
Protocol Analytical Supplies	472 Lincoln Blvd Middlesex, NJ 08846 732-627-0500 FAX 732-627-0979 Bhahn@prostds.com	William H. Hahn
RT Corporation	P.O. Box 1346 Laramie, WY 82073 307-742-5452 or 800-576-5690 FAX 307-745-7936 RT-Corp@RT-Corp.com	Bob Rucinski

## HAZARDOUS WASTE METHODS (January 2000)

#### Inorganic Compounds & Elements

antimony arsenic barium beryllium cadmium chromium, total cobalt copper lead mercury molybdenum nicke1 selenium silver thallium vanadium zinc chromium (VI) \* cyanide \*\* fluoride \*\* organo lead \* sulfide \*\*

#### Physical Properties

corrosivity - pH \*
ignitability - flashpoint \*
reactivity \*

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

<sup>\*\*</sup>Sample to be available in the Summer of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 2 of 15

#### CA Method LUFT

gasoline diesel

#### EPA Method 418.1

petroleum hydrocarbons

#### EPA Method 8010B

carbon tetrachloride chloroform chloromethane 1.2-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene 1,1-dichloroethane 1,2-dichloroethane dichloromethane 1,1,2,2-tetrachloroethane 1,1,1,2-tetrachloroethane tetrachloroethene 1,1,1-trichloroethane 1,1,2-trichloroethane trichloroethene trichlorofluoromethane 1,2,3-trichloropropane vinylchloride

#### EPA Method 8011

1,2-dibromo-3-chloropropane (DBCP) ethylene dibromide (EDB)

\* Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 3 of 15

#### EPA Method 8015B\*

allyl alcohol
t-butyl alcohol
1,4-dioxane
ethylene glycol
methanol
methylisobutylketone (MIBK)
N-nitroso-di-n-butylamine
paraldehyde
2-pentanone
pyridine
o-toluidine

#### EPA Method 8015B (TPH only)

gasoline diesel

#### EPA Method 8020A

benzene
chlorobenzene
1,2-dichlorobenzene
1,3-dichlorobenzene
1,4-dichlorobenzene
ethylbenzene
toluene
xylenes

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 4 of 15

#### EPA Method 8021B (halogenated volatiles only)

bis(2-chloroisopropyl)ether bromobenzene bromoform carbontetrachloride chloroform. chloromethane 1,2-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene dichlorodifluoromethane 1.1-dichloroethane 1,2-dichloroethane 1,1,1,2-tetrachloroethane 1,1,2,2-tetrachloroethane tetrachloroethene 1,2,4-trichlorobenzene 1,1,1-trichloroethane 1,1,2-trichloroethane trichloroethene 1,2,3-trichloropropane vinylchloride

#### EPA Method 8021B (Aromatic Volatiles only)

benzene chlorobenzene 1,2-dichlorobenzene 1.3-dichlorobenzene 1,4-dichlorobenzene ethy1benzene toluene xylenes

#### EPA Method 8021B (BTEX and MTBE only)

benzene toluene ethy1benzene xylenes methyl-t-butylether

#### EPA Method 8031\*

acrylonitrile

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 5 of 15

#### EPA Method 8032A\*

acrylamide

#### EPA Method 8041

4-chloro-3-methylphenol
2-chlorophenol
2-methylphenol (o-cresol)
3-methylphenol (m-cresol)
4-methylphenol (p-cresol)
2,4-dimethylphenol
2-nitrophenol
4-nitrophenol
pentachlorophenol
phenol
2,3,4,5-tetrachlorophenol
2,3,4,6-tetrachlorophenol
2,3,5,6-tetrachlorophenol
2,4,5-trichlorophenol
2,4,5-trichlorophenol

#### EPA Method 8061A\*

bis(2-ethy]hexy])phthalate butylbenzylphthalate di-n-butylphthalate diethylphthalate dimethylphthalate di-n-octylphthalate

bis(2-methoxyethy1)phthalate diamylphthalate dicyclohexylphthalate dinonylphthalate hexyl-2-ethylhexylphthalate

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 6 of 15

#### EPA Method 8070A\*

N-nitrosodimethylamine N-nitrosodiphenylamine N-nitrosodi-n-propylamine

#### EPA Method 8081A (Organochlorine Pesticides only)

aldrin alpha-BHC beta-BHC delta-BHC gamma-BHC alpha-chlordane gamma-chlordane chlordane 4,4'-DDD 4,4'-DDE 4,4'-DDT dieldrin endosulfan I endosulfan II endosulfate endrin heptachlor heptachlor epoxide methoxychlor toxaphene

#### EPA Method 8082 (PCBs only)

aroclor 1016/1242 aroclor 1221 aroclor 1232 aroclor 1248 aroclor 1254 aroclor 1260

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Wast Methods (January 2000) Page 7 of 15

#### EPA Method 8091\*

1,4-dinitrobenzene
2,4-dinitrotoluene
2,6-dinitrotoluene
1,4-naphthoquinone
nitrobenzene
pentachloronitrobenzene

1-chloro-2,4-dinitrobenzene 1-chloro-4-nitrobenzene 4-chloro-3-nitrotoluene 3,5-dichloronitrobenzene

dinitramine
1,2-naphthoquinone
2-nitrotoluene
2,3,4,5-tetrachloronitrobenzene
2,4,6-trichloronitrobenzene
trifluralin

#### EPA Method 8100

acenaphthene acenaphthylene anthracene benzo(a)anthracene benzo(a)pyrene benzo(b)fluoranthene benzo(k)fluoranthene benzo(g,h.i)perylene chrysene dibenzo(a,h)anthracene fluoranthene fluorene indeno(1,2,3-c,d)pyrene napthalene phenanthrene pyrene

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 8 of 15

#### EPA Method 8111\*

4-bromophenylphenylether 2-chlorophenyl-4-nitrophenylether 3-chlorophenyl-4-nitrophenylether 4-chlorophenyl-4-nitrophenylether 2,4-dibromophenyl-4-nitrophenylether 2.4-dichlorophenyl-3-methyl-4-nitrophenylether 2.6-dichlorophenyl-4-nitrophenylether 3,5-dichlorophenyl-4-nitrophenylether 2,5-dichlorophenyl-4-nitrophenylether 2,4-dichlorophenyl-4-nitrophenylether 2,3-dichlorophenyl-4-nitrophenylether 3.4-dichlorophenyl-4-nitrophenylether 4-nitrophenylphenylether 2,4,6-trichlorophenyl-4-nitrophenylether 2,3,6-trichlorophenyl-4-nitrophenylether 2,3,5-trichlorophenyl-4-nitrophenylether 2,4,5-trichlorophenyl-4-nitrophenylether 3,4,5-trichlorophenyl-4-nitrophenylether 2,3,4-trichlorophenyl-4-nitrophenylether

#### EPA Method 8120A\*

2-chloronaphthalene
1,2-dichlorobenzene
1,3-dichlorobenzene
1,4-dichlorobenzene
hexachlorobenzene
hexachlorobenzene
hexachlorobutadiene
hexachlorocyclohexane
hexachlorocyclopentadiene
hexachloroethane
pentachlorohexane
tetrachlorobenzenes
1,2,4-trichlorobenzene

\* Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 9 of 15

#### EPA Method 8121\*

benzal chloride
benzotrichloride
alpha-BHC (alpha-hexachlorocyclohexane)
beta-BHC (beta-hexachlorocyclohexane)
gamma-BHC (gamma-hexachlorocyclohexane)
delta-BHC (delta-hexachlorocyclohexane)
pentachlorobenzene
1,2,3,4-tetrachlorobenzene
1,2,4,5-tetrachlorobenzene
1,2,3,5-tetrachlorobenzene
1,2,3-trichlorobenzene
1,3,5-trichlorobenzene

#### EPA Method 8141A\*

diazinon
dichlorvos (DDVP)
melathion
phorate
ronnel
stirophos (tetrachlorovinphos)

#### EPA Method 8150B

```
2,4-D (2,4-dichlorophenoxyacetic acid)
2,4-DB
2,4,5-T
2,4,5-TP (silvex)
dalapon
dicamba
dinoseb
MCPP
```

#### EPA Method 8151A

```
2,4-D (2,4-dichlorophenoxyacetic acid)
2,4-DB
2,4,5-T
2,4,5-TP (silvex)
dalapon
dicamba
dinoseb
MCPP
pentachlorophenol
```

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 10 of 15

#### EPA Method 8240B

benzene
chlorobenzene
1,2-dichlorobenzene
1,3-dichlorobenzene
1,4-dichlorobenzene
ethylbenzene
isopropylbenzene
toluene
xylene

bis(2-chloroethyoxymethane) bis(2-chloroethyl)ether bis(2-chloroisopropyl)ether carbontetrachloride chloroacetaldehyde chloroform chloromethane 1,1-dichloroethane 1,2-dichloroethane 1,1,1,2-tetrachloroethane 1,1,2,2-tetrachloroethane tetrachloroethene trichloroethene trichlorofluoromethane 1,2,3-trichloropropane viny1ch1oride

#### EPA Method 8250A

aniline

acenaphthene acenaphthylene anthracene benzo(a)anthracene benzo(a)pyrene benzo(b)fluoranthene benzo(k)fluoranthene benzo(g,h.i)perylene chrysene dibenzo(a,h)anthracene fluoranthene fluorene indeno(1,2,3-c,d)pyrene napthalene phenanthrene pyrene

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 11 of 15

#### EPA Method 8250A (continued)

diethylphthalate di-n-octylphthalate dimethylphthalate

gamma-BHC 4,4'-DDT endrin heptachlor heptachlor epoxide pentachlorophenol toxaphene

2-chloronaphthalene hexachlorobenzene hexachloroethane

#### EPA Method 8260B

benzene chlorobenzene 1,2-dichlorobenzene 1,3-dichlorobenzene 1,4-dichlorobenzene ethylbenzene isopropylbenzene toluene xylene

carbontetrachloride
chloroform
chloromethane
1,1-dichloroethane
1,2-dichloroethane
hexylchloroethane
methanol
1,1,1,2-tetrachloroethane
1,1,2,2-tetrachloroethane
tetrachloroethene
trichloroethene
trichloroethene
trichlorofluoromethane
1,2,3-trichloropropane
vinylchloride

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 12 of 15

#### EPA Method 8270C

2-amino-1-methylbenzene (o-toluidine) aniline maleic anhydride

acenaphthene acenaphthylene anthracene benzo(a)anthracene benzo(a)pyrene benzo(b)fluoranthene benzo(k)fluoranthene benzo(g,h.i)perylene chrysene dibenzo(a,h)anthracene fluoranthene fluorene indeno(1,2,3-c,d)pyrene napthalene phenanthrene pyrene

diethylphthalate di-n-octylphthalate dimethylphthalate

gamma-BHC 4,4'-DDT endrin heptachlor heptachlor epoxide pentachlorophenol toxaphene

#### EPA Method 8280A\*

TCDD PeCDD HxCDDs HpCDD OCDD TCDF

PeCDFs HxCDFs

**HpCDFs** 

OCDF

\_\_\_\_\_\_

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 13 of 15

#### EPA Method 8290\*

TCDD
PeCDD
HxCDDs
HpCDD
OCDD
TCDF
PeCDFs
HxCDFs
HpCDFs

OCDF

#### EPA Method 8310

acenaphthene acenaphthylene anthracene benzo(a)anthracene benzo(a)pyrene benzo(b)fluoranthene benzo(k)fluoranthene benzo(g,h.i)perylene chrysene dibenzo(a,h)anthracene fluoranthene fluorene indeno(1,2,3-c,d)pyrene napthalene phenanthrene pyrene

#### EPA Method 8315A\*

acetaldehyde acetone acrolein benzaldehyde cyclohexanone formaldehyde octanal m-tolualdehyde o-tolualdehyde p-tolualdehyde

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 14 of 15

#### EPA Method 8316\*

acrylamide acrylonitrile acrolein

#### EPA Method 8318\*

aldicarb (temik)
aldicarb sulfone
carbaryl (sevin)
carbofuran (furadan)
dioxacarb
3-hydroxycarbofuran
methiocarb (mesurol)
methomyl (lannate)
promecarb
propoxur (baygon)

#### EPA Method 8321A

Aldicarb
aldicarb sulfone
aldicarb sulfoxide
carbaryl
carbofuran
diuron
methiocarb (mesurol)
methomyl (lannate)
propoxur (baygon)

#### EPA Method 8330\*

```
HMX (octahydro-1,3,5,7-tetranitro-1,3,5,7-tetrazocine)
RDX (hexahydro-1,3,5-trinitro-1,3,5-triazine)
1,3,5-TNB (1,3,5-trinitrobenzene)
1,3,-DNB (1,3,-dinitrobenzene)
tetryl (methyl-2,4,6-trinitrophenylnitramine)
NB (nitrobenzene)
2,4,6-TNT (2,4,6-trinitrotoluene)
4-Am-DNT (4-amino-2,6-dinitrotoluene)
2-Am-DNT (4-amino-4,6-dinitrotoluene)
2,4-DNT (2,4-dinitrotoluene)
2,6-DNT (2,6-dinitrotoluene)
2-NT (2-nitrotoluene)
3-NT (3-nitrotoluene)
4-NT (4-nitrotoluene)
```

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.

Hazardous Waste Methods (January 2000) Page 15 of 15

#### EPA Method 8331\*

tetrazene


#### EPA Method 8410


acenaphthene
acenaphthylene
anthracene
benzo(a)anthracene
benzo(a)pyrene
chrysene
dibenzofuran
fluoranthene
fluorene
napthalene
phenanthrene
pyrene

bis(2-ethylhexyl)phthalate di-n-butylphthalate diethylphthalate di-n-octylphthalate dimethylphthalate

pentachlorophenol

<sup>\*</sup> Sample to be available in the Spring of 2000. Laboratories certified or seeking certification for the method are required to analyze the appropriate study sample from that time.





## ELAP HW STUDY REQUIREMENTS (Vendor Information)

Laboratories certified by California ELAP will be notifying vendors that they will be requiring participation in performance evaluation studies. These laboratories may provide lists of the analytes needed. The studies have been scheduled for the first and third quarters of the calendar year. Laboratories are recommended to participate in the necessary studies during the scheduled three-month windows. Completion dates of the studies may be beyond the three-month period. Each study shall be no longer than 45-days in length. Evaluation reports shall be provided to the laboratory and ELAP by the vendor within 21 days of the study completion date.

- 2. Those laboratories electing not to follow the Department's schedule are responsible for timely submittal of evaluation reports by the chosen vendor(s) to ELAP. Such reports must be received at ELAP from the chosen vendor(s) no later than June 30th of each calendar year for the first study, and no later than December 31st of each calendar year for the second study. (Evaluation reports received after the designated dates, June 30th and December 31st, will not be accepted, i.e. no laboratory will be subject to preferential treatment. Faxed copies of the reports are not accepted.) The two studies are recommended to be approximately six months apart. Each study shall be no longer than 45-days in length as designated by the vendor. Evaluation reports shall be provided to the laboratory and ELAP by the vendor within 21 days of the study completion date.
- The vendor must be in compliance with NIST handbook 150, NIST handbook 150-19, USEPA criteria document (December 1998 & updates), and NELAC standards. The vendor must also be in compliance with ISO/IEC Guide 43-1 (1999(E)).

The list of analytes are sectioned by method, so that the laboratories will know which representative analytes by method are required for performance evaluation study purposes.

- 5 Laboratories are required to obtain acceptable rating in performance evaluation studies, once a year, for all fields-of-testing certified or sought for certification.
- 6. The evaluation report must have the following minimum information

vendor's name, ID number, location, telephone, fax
type of sample and matrix (e.g. solid, non-aqueous liquid)
study dates (beginning & completion), study number
laboratory (participant) name, city, state
(if mobile, license number, vehicle identification number)
laboratory EPA ID code
analytes
method of analyses
reported results
acceptance range
MDL (method detection limit assigned by the vendor)
mean
evaluation of "acceptable" or "not acceptable"
overall method evaluation of "acceptable" or "not acceptable"

ELAP HW Study Requirements Vendor Information Page 2 of 2

The evaluation reports must be similar to past USEPA reports, i.e. the analytes, etc. should be on the same sheet, rather than on individual sheets. The vendor must comply with the USEPA Criteria Document with respect to database field identifications and format, with the exception of the additional fields, such as MDL.

The address and contact for mailing of evaluation report(s is

Fred Choske Environmental Laboratory Accreditation Program California State Department of Health Services 2151 Berkeley Way, Annex 2 Berkeley, CA 94704.

Faxed copies of the evaluation report are not accepted

Electronically transmitted evaluation report(s) in fixed width ASCII Microsoft Access or Microsoft Excel format should be E-mailed to



10 Both printed and electronica y transmitted evaluation reports are required for California ELAP.

Contact for specifications and general questions from vendors should be directed to

Jane Jensen at 510) 540-2800 or FAX 510) 849-5106

### HAZARDOUS WASTE PERFORMANCE EVALUATION SAMPLE REQUIREMENTS

#### Solid Matrices

Samples must be  $\underline{\text{close}}$  to real world samples similar to matrix routinel encountered as hazardous waste. Solids may be ash, soil, paint chips sediment, sludge, or other similar hazardous waste solids.

2 Samples cannot be sand.

Samples cannot be blanks or background solids.

Samples <u>cannot</u> be spikes which are provided in separate containers one containing a matrix and the other containing the spiking solution.

The sample must be a composite sample, provided in one contained

#### Non-aqueous Liquid Matrices

Samples must be  $\underline{\text{close}}$  to real world samples similar to matrix routinely encountered as hazardous waste. Non-aqueous liquid matrices may be oils, paint, tar, or other similar hazardous waste non-aqueous liquids.

Samples cannot be blanks or background non-aqueous liquids.

- Samples <u>cannot</u> be spikes which are provided in separate containers one containing a matrix and the other containing the spiking solution.
- 4 The sample must be a composite sample, provided in one container

#### General Requirements

Samples must be stable for a minimum of 60 days.

Samples must be checked for homogeneity.

Samples must be validated for determination of acceptance imits

#### Contact

The contact person for further specifications and information is

Jane Jensen Department of Health Services 2151 Berkeley Way, Annex 2 Berkeley, CA 94704 (510) 540-2800 FAX 849-5106. HAZARDOU: WAS PERFORMANCE: EVALUATION MPLE ECIFICA (Vendor Information O

#### rganic Analytes

The sample must be de the such that multiple methods for VOC analyses can be used to ident appropriate analytes.

There should be a single sample containing semi-volatile compounds.

sample must be designed such that multiple methods for semi-volatile analyses can be used to identify the appropriate analytes.

Separate samples can be provided for those special cases where physicand chemical properties of the analytes, safety, or other limiting fact exist. Examples are carbamates, dioxins, explosives, herbicides, PCB PAHs, and pH.

The analyte composition in following studies need not be the same the same analytes need not be present in every study.

#### organic Analytes

There should be one sample for metals analyses.

circumstances for "specia analyte compositions" may be due to phy and chemical properties of the analytes, safety, or othe lim factors.

Hazardous Waste Performance Evaluation Sample Specification Vendor Information Only Page 2 of 3

#### General Specifications


Reports/Instructions

The report forms, which are provided to participants with the samples, must have the analytes that are present, and those that are not present (i.e. the forms must incorporate representative analytes whether present or not). The report forms must also have the MDL (method detection limit) for each analyte that the participants are expected to meet.

The vendor should provide instructions to participants. An example has been enclosed for information purposes. The sample size and aliquot size are recommended values.

Study instructions to participants for analyses of TPH (gasoline/diese must contain the spectrum cut off range (i.e., GROs and DROs) for analyses.

The vendor must list a method detection limit (MDL) for each analyte. The MDL can be a value from the approved method, or a value which is targeted by the vendor as a minimum detection value for the analyte in the sample.



The random number generator shall be used to determine the concentration of the analyte for the study.

The samples must be subjected to homogeneity checks, as specified in the ISO/IEC Guide 43-1 (1996(E)). The samples must meet homogeneity requirements at the 95% confidence level.

The samples must be subjected to shelf life stability studies as described in ISO/IEC Guide 43-1 (1996(E)).

The samples must be validated for the determination of acceptance limits. Use of linear regression equations are not accepted, since they are not applicable for the types of sample matrices described in this document. Validation shall be conducted by reference laboratories, as described in ISO/IEC Guide 43-1 (1996(E)). A minimum of twenty data points per analyte per sample is preferred, but if less than 20 data points are only attainable, Horowitz statistics or similar statistics shall be utilized to determine the mean and standard deviation.

Validation for the determination of acceptance limits must involve the use of California approved method(s) of analyses for the compounds in the hazardous waste sample(s). Lists of approved methods are available on our Web, www.dhs.ca.gov/ps/ls/elap/elapindex.htm, in the laboratory information forms (LIF) for hazardous waste fields-of-testing 9, 10, 11, 12, and 13.

The quantity of sample provided to the participant must be sufficient to carry out the analyses as a routine real world sample. Since more than one method may be used on the same sample, sufficient sample must be provided. However, the sample quantity should be limited to the degree that there would be insufficient sample quantity for duplicate matrix spikes and other quality control parameters for each method employed.

8

#### Evaluation

For evaluation of laboratory results, any false negative or false positive result must be evaluated as "not acceptable". Any value reported below the listed MDL shall be evaluated as "acceptable".

The frequency of solid vs non-aqueous liquid matrices in performance evaluation studies should be planned in such a manner that a variety of matrices would be made available to laboratories, but would restrict it in such a way that a laboratory obtaining "not acceptable" rating for a method with a matrix will have an opportunity to be retested at a later date with a similar matrix.

- Acceptance limits are based on mean and standard deviation from reference laboratory data. The acceptance limits are determined by Z-score statistics at the 99% confidence level.
- 4. Since certification for organic fields-of-testing are by methods, the organic analytes in a performance evaluation study are evaluated individually and the overall evaluation by method must also appear in the evaluation report.

Since certification for inorganic fields-of-testing are by individual analyte, the inorganic analytes in a performance evaluation study are evaluated individually and the evaluation report must have the method of analysis for the analyte.

EXAMP F

## INSTRUCTIONS HAZARDOUS WASTE PERFORMANCE EVALUATION STUDY HW04

CAUTION: read the instructions carefully before beginning the analyses

The samples are hazardous waste solids and non-aqueous liquids containing inorganic and organic compounds as indicated on the report forms. The samples must be analyzed by methods for which your laboratory is certified and/or seeking certification in the hazardous waste fields-of-testing. The analyst(s) performing the analyses must be the analyst(s)who routinely performs hazardous waste analyses.

Each laboratory is required to identify and quantitate the compounds in each sample for which the laboratory is certified and/or seeking certification. Any false positive or false negative response will be evaluated as "not acceptable". Also evaluated as "not acceptable" will be results of "<" values exceeding the method detection limits provided on the report forms.

The samples are provided in limited quantities. Laboratories are advised to plan ahead before beginning sample preparation. There may be insufficient sample for duplicates and matrix spikes. The table below shows the recommended aliquot size by matrix and analyte. Non-aqueous liquid sample sizes will vary by type of liquid and analyte composition, and recommended aliquot size will be provided with the sample. (The "soil" designation in the table applies to sludge, sediment and other soil-like matrix.)

matrix	sample size(g)	analyte	aliquot (g)
ash paint chips powder soil soil soil soil soil soil	30 - 50 20 20 30 50 100 100 30 30	metals metals metals CN/F/S metals organic TPHdiesel TPHgasoline VOC	1 - 2 1 - 2 1 - 2 10 1 - 2 30 10 9 10

#### **Data Reporting**

Copies of the blank report forms should be made to facilitate reporting of results from multiple methods for the same analyte. Each laboratory is required to meet the "detection limits" provided on the report forms. If the response is non-detect, the "ND" or "<" with the method detection limit must be entered. All data must be reported to three (3) significant figures based on dry weight (with the exception of explosive compounds) in units of mg/Kg. (For liquid matrix, the units for reporting is mg/L.) If an analyte was not analyzed, the result field next to that analyte must be left blank.

#### Inquiries